

Date: Wednesday, 27/08/2008 12:53:59 PM
 User: Julie Lecocq

Process Sheet

Customer	: CU-DAR001 Dart Helicopters Services	Drawing Name	: BO 105 SKIDTUBE ASSEMBLY
Job Number	: 41639		
Estimate Number	: 10112		
P.O. Number	:	Part Number	: D105674011G
This Issue	: 27/08/2008 S.O. No. :	Drawing Number	: D2966 REV A2
Prsht Rev.	: NC	Project Number	: N/A
First Issue	: / / Type : SKIDTUBES	Drawing Revision	: A2
Previous Run	: 35981	Material	:
Written By	:	Due Date	: 10/09/2008 Qty: 1 Um: Each
Checked & Approved By	: <u>JLD 08.8.26</u>		
Comment	: Est Rev:A 04.07.07 New Issue KJ/JLM		

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	DC	DOCUMENT CONTROL
-----	----	------------------



JLD 08.8.28



Comment: DOCUMENT CONTROL

Photocopy bluefile & type labels per PPP d105-674-011G CHG002

JLD 08.8.28

2.0	D2962125	Outer Tube Extrusion
-----	----------	----------------------



Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)

Pick:

Qty Part Number Description Batch

1 D2962-125 Extrusion 17532

JLD 08.08.27

3.0	SKIDTUBES 1	SKIDTUBESS RESOURCE 1
-----	-------------	-----------------------



Comment: LANDING GEAR RESOURCE 1

1-Determine square end of tube and deburr

2-Drill #30 pilot holes using DT8678. Open holes to Ø5/16" (0.313"). Deburr holes.

JLD 08.08.27

4.0	BENDING	BENDING MACHINE - SKIDTUBES
-----	---------	-----------------------------



Comment: BENDING MACHINE

Bend tube as per program BO105 on CNC Bender and Dwg D2966. Use 5/16" locator pin on buggy "A".

JLD 08.08.27

5.0	SKIDTUBES 1	SKIDTUBESS RESOURCE 1
-----	-------------	-----------------------



Comment: LANDING GEAR RESOURCE 1

1-Cut Fwd end of the tube using DT8185-1G

JLD 08.08.27

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 27/08/2008 12:53:59 PM
User: Julie Lecocq

Process Sheet

Grey

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BO 105 SKIDTUBE ASSEMBLY

Job Number: 41639

Part Number: D105674011G

Job Number:



Seq. #:

Machine Or Operation:

Description :

2-Cut Aft end at 107.06" using DT8185D

3-Deburr ends

4-Drill Aft Cap holes using DT8678

5-Locate DT8679 with 1/8 clecos in Aft Cap holes. Ensure DT8679 is centered on Fwd end of tube and drill #40 Fwd bushing.

6-Clamp DT8679 to the tube. Drill all #30 wearplate and crossbolt holes.

7-Open Aft Cap holes using #6 drill

8-Open wearplate holes and two side holes to Ø19/64" (0.297") as per Dwg D2966-1.

9-Deburr holes.

10-Open remaining (16) crossbolt holes to Ø0.500

8T
08-08-28

6.0

D2964

Cap



Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)

Pick:

Qty Part Number Description Batch

1 D2964

Cap

14101

A/R

Aluminum Rod

M 108708/m 107877

BE 08-08-29

7.0

SKIDTUBES 1

SKIDTUBESS RESOURCE 1



Comment: LANDING GEAR RESOURCE 1

1-Weld Fwd Cap as per Dwg D2966 and QSI 004. Fill #40 Fwd cleco hole.

BE 08/08/29

2-Grind Fwd Cap welds flush

JD 8-8-29

8.0

QC10

VISUAL INSPECTION OF GROUND WELDS



Comment: VISUAL INSPECTION OF GROUND WELDS

S 08/08/29

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 27/08/2008 12:53:59 PM
User: Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BO 105 SKIDTUBE ASSEMBLY

Job Number: 41639

Part Number: D105674011G

Job Number:



Seq. #:

Machine Or Operation:

Description :

9.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

508/08/09 @

10.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Chemical Conversion Coat as per QSI 005 4.1

25 08-09-02

11.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

D M 8-9-2

12.0

SKIDTUBES 1

SKIDTUBESS RESOURCE 1



Comment: LANDING GEAR RESOURCE 1

1-Open crossbolt holes to finish size as per Dwg D2966

2-Open 14 holes to Ø0.750" & 2 holes to Ø0.875", countersink crossbolt holes & remove alodine to prepare for welding as per Dwg D2966

3-Deburr holes inside & outside, blow out chips

ST
08-09-02

13.0

D2976

BO 105 Skidtube I Beam



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

Pick:

Qty Part Numbe

Description Batch

1 D2976 Web

B-4/261

AWM

8-9-2

14.0

D2971

Cross Bolt Spacer



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

Pick:

Qty Part Number

Description Batch

1 D2971 Crossbolt Spacer

B39011

BE 8-9-3

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 27/08/2008 12:53:59 PM
User: Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BO 105 SKIDTUBE ASSEMBLY

Job Number: 41639

Part Number: D105674011G

Job Number:



Seq. #:

Machine Or Operation:

Description :

15.0

D2973

Cross Bolt Spacer



Comment: Qty.: 7.0000 Each(s)/Unit Total: 7.0000 Each(s)

Pick:

Qty Part Number Description Batch

7 D2973 Crossbolt Spacer

BE 8-9-3

16.0

SKIDTUBES 1

SKIDTUBESS RESOURCE 1



Comment: LANDING GEAR RESOURCE 1

1-Bond Web in place per QSI 015. (Ensure holes line up)

Pick:

Qty Part Number Description Batch

A/R Sikaflex-291

Sikaflex expiry date :

M108801
8-10-01

AWM
8-9-2

2-Weld Crossbolt Spacers as per Dwg D2966 and QSI 004. For crossbolt spacer, weld one side, pass 5/8" drill; weld other side, pass 5/8" drill.

Pick:

Qty Part Number Description Batch

A/R Aluminum Rod

M108708 BE 8-9-3

3-Pass Ø0.630" drill to remove spillover for D2973 crossbolt. Pass Ø0.750" drill to remove spillover for D2971 crossbolt.

BE 8-9-3

4-Grind welds flush as per Dwg D2966

JD 8-9-4

17.0

QC10

VISUAL-INSPECTION OF GROUND WELDS



Comment: VISUAL INSPECTION OF GROUND WELDS

08/09/05 @

18.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

08/09/05 @

19.0

HAND FINISHING1

HAND FINISHING RESOURCE #1




Comment: HAND FINISHING RESOURCE #1

Powder Coat Grey Sandtex (Ref: 4.3.5.6) as per QSI 005 4.3

pressure wash # 09-09-08

M106842

FL 08/09/08

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
08/09/08	19.0	start time : 8:40 Temp : 320° Finish time : 9:10	FL	08/09/08	①		

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 27/08/2008 12:53:59 PM
User: Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BO 105 SKIDTUBE ASSEMBLY

Job Number: 41639

Part Number: D105674011G

Job Number:



Seq. #:

Machine Or Operation:

Description :

20.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



HL



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

08-09-09- (X)

21.0

D2965

Cap, 105 Skidtube



X

Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)

Pick:

Qty Part Number

Description Batch

1 D2965

Cap

B41885

m-h

22.0

D29701

Wearplate



Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)

Pick:

Qty Part Number

Description Batch

1 D2970-1

Wearplate

B33220

m-h

23.0

D29703

Wearplate



X

Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)

Pick:

Qty Part Number

Description Batch

1 D2970-3

Wearplate

B12322

m-h

24.0

D31761

Bushing



Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)

Pick:

Qty Part Number

Description Batch

1 D3176-1

Bushing

B33222

m-h

25.0

D31763

Nut



(X)

Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)

Pick:

Qty Part Number

Description Batch

1 D3176-3

Nut

B37585

m-h 08/09/09

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 27/08/2008 12:53:59 PM
User: Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BO 105 SKIDTUBE ASSEMBLY

Job Number: 41639

Part Number: D105674011G

Job Number:



Seq. #:

Machine Or Operation:

Description :

26.0

ALS71032130

Insert



Handwritten mark: A

Comment: Qty.: 36.0000 Each(s)/Unit Total: 36.0000 Each(s)

Pick:

Qty Part Number Description Batch

36 ALS7-1032-130 Insert

or ALS4-1032-130

or AKS7-1032-130

or AKS4-1032-130

Handwritten: M105819

Handwritten: m-l

27.0

AN960JD10L

Washer



Comment: Qty.: 28.0000 Each(s)/Unit Total: 28.0000 Each(s)

Pick:

Qty Part Number Description Batch

28 AN960JD10L Washer

Handwritten: M105793

Handwritten: m-l

28.0

MS27039108

Screw



Comment: Qty.: 26.0000 Each(s)/Unit Total: 26.0000 Each(s)

Pick:

Qty Part Number Description Batch

26 MS27039-1-08 Screw

Handwritten: M109061

Handwritten: m-l

29.0

MS27039109

Screw



Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s)

Pick:

Qty Part Number Description Batch

2 MS27039-1-09 Screw

Handwritten: M108057

Handwritten: M108057

Handwritten: m-l

30.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Handwritten: (X)

Comment: HAND FINISHING RESOURCE #1

1-Inspect for foreign objects as per QSI 024

2-Install Inserts, Wearplate and Cap per Dwg D2966. Insert a drop of sikaflex at insert holes before installing wearplates. Seal Aft Cap using Sikaflex. Install bushing and nut. By looking Fwd, install nut to right hand side.

Pick:

Handwritten: m-l 08/09/09

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BO 105 SKIDTUBE ASSEMBLY

Job Number: 41639

Part Number: D105674011G

Job Number:



Seq. #:

Machine Or Operation:

Description :

Qty Part Number Description Batch

A/R Sikaflex-291

Sikaflex expiry date:

M108443 m-l 08/04/09
08/11

3-Wing Walk as per Dwg D2966 and QSI 005 4.4

Batch:

11107892

7

JS

08-08-08

(21)

31.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

8 08/02/07

32.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

*****ENSURE INSERT ARE AT LOCATION (6) AS PER DWG D2966*****

8 08/02/09

33.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Pick: Packing Kit

34.0

D2972

Bushing



Comment: Qty.: 6.0000 Each(s)/Unit Total: 6.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description Batch

6 D2972

Bushing

14103

JS 08/09/11 (21)

35.0

D2974

Packer



Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description Batch

1 D2974

Packer

31249

JS 08/09/11 (21)

36.0

D2975

Wearshoe



Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description Batch

2 D2975

Wearplate

29538

Batch not in comp

JS 08/09/11 (21)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 27/08/2008 12:53:59 PM
User: Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BO 105 SKIDTUBE ASSEMBLY

Job Number: 41639

Part Number: D105674011G

Job Number:



Seq. #:

Machine Or Operation:

Description :

37.0

AN451A

Bolt



Comment: Qty.: 3.0000 Each(s)/Unit Total : 3.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description Batch

3 AN4-51A Bolt

108376

JS 08/09/11 (X)

38.0

AN960JD10L

Washer



Comment: Qty.: 8.0000 Each(s)/Unit Total : 8.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description Batch

8 AN960JD10L Washer

M105793

JS 08/09/11 (X)

39.0

MS21042L4

Nut



Comment: Qty.: 3.0000 Each(s)/Unit Total : 3.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description Batch

3 MS21042L4 Nut

M167499

JS 08/09/11 (X)

40.0

MS27039108

Screw



Comment: Qty.: 8.0000 Each(s)/Unit Total : 8.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description Batch

8 MS27039-1-08 Screw

M169001

JS 08/09/11 (X)

41.0

QC4

INSPECT 100% KITS FOR COMPLETENESS



Comment: INSPECT 100% KITS FOR COMPLETENESS

JS 08/09/11 (X)

42.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and pack for shipping as per PPP D105-674-011G

Location: 82

8/9/11

(X)

SP

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 27/08/2008 12:53:59 PM
User: Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BO 105 SKIDTUBE ASSEMBLY

Job Number: 41639

Part Number: D105674011G

Job Number:



Seq. #:

Machine Or Operation:

Description :

43.0

QC21

FINAL INSPECTION/W/O RELEASE



08/09/12 *[Signature]*

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



u 08-09-12

BO 41639

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



DESIGN RF	DRAWN BY RF	DART AEROSPACE USA, INC. BELLEVUE, WA	
CHECKED #	APPROVED #	DRAWING NO. D2966	REV. A SHEET 1 OF 2
DATE 00.03.08		TITLE BO 105 SKIDTUBE ASSEMBLY SCALE NTS	
A	00.03.08	NEW ISSUE	

RELEASED
00-05-11 #

Qty	Part Number	Description
X	D2966-041	SKIDTUBE ASSEMBLY
1	D2962-125	EXTRUSION
1	D2964	CAP
1	D2965	CAP
1	D2970-1	WEARPLATE
1	D2970-3	WEARPLATE
1	D2971	CROSS BOLT SPACER
7	D2973	CROSS BOLT SPACER
1	D2976	WEB
36	ALS7-1032-130 or ALS4-1032-130 or AKS7-1032-130 or AKS4-1032-130	INSERT
28	AN960JD10L	WASHER
26	MS27039-1-08	SCREW
2	MS27039-1-09	SCREW
1	D3176-1	BUSHING
1	D3176-3	NUT



GENERAL NOTES:

- 1) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 2) WELDING TO BE DONE PER DART QSI 004.
- 3) INSERT D2976 WEB TO LOCATION SHOWN OFF AFT END OF SKIDTUBE AND BOND WEB INTO OUTER TUBE WITH NON-STRUCTURAL SIKAFLEX-241/-291 ADHESIVE PER DART QSI 015 AFTER BENDING.
- 4) USE DART DRILL TEMPLATE DT8451 TO LOCATE AND DRILL Ø0.297 HOLES FOR WEARSHOE INSERTS. INSTALL ALS7-1032-130 PER SECTION B-B (34 PLACES) AFTER FINISH. SEAL WEARPLATE SCREWS WITH SIKAFLEX-241/-291.
- 5) DO NOT INSTALL MS27039-1-08 SCREWS AND AN960JD10L WASHERS IN THESE LOCATIONS.
- 6) INSTALL ALS7-1032-130 INSERT, MS27039-1-08 SCREW, AND AN960JD10L WASHER IN 2 PLACES THIS LOCATION BEFORE POWDER COATING.
- 7) FINISH:

ACID ETCH, ALODINE PER DART QSI 005 4.1 PRIOR TO INSERTING D2976 WEB
POWDER COAT ASSEMBLY GLOSS WHITE (REF 4.3.5.4) PER DART QSI 005 4.3
BLACK ANTI-SKID PAINT AS INDICATED TO 1.00 ABOVE CENTER LINE PER DART
QSI 005 4.4 (OPTIONAL) BLACK SANDTEX (REF 4.3.5.7)










01.01.24
IP 01.01.30

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 41639

A2	02.10.30	ADD D3176-1/-3	# IP
A1	01.01.24	CHANGE COLOR TO BLACK SANDTEX	# IP

Copyright © 2000 by DART AEROSPACE USA, INC.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.



COPYRIGHT © 2000 BY DART AEROSPACE USA, INC.		DESIGN RF	DRAWN BY RF	DART DART AEROSPACE USA, INC. BELLINGHAM, WA	
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.		CHECKED A	APPROVED A	DRAWING NO. D2966	REV. A SHEET 2 OF 2
		DATE 00.03.08		TITLE BO 105 SKIDTUBE ASSEMBLY	SCALE 1:20

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
41639

RELEASED
00-05-11

NO. 172

AWS D17.1.2001
QUALIFICATION TEST RECORD

Name: Barclay Elliot
Job number: 41331
Part number: D105 674 011
Description: B0105 skid tube
Welding Process: Tig[☒] Mig[]
Base material: Aluminium
Current: AC[☒] DC[]

TEST REQUIREMENTS AND RESULTS

Visual: pass[☒] fail[]
Penetration: pass[☒] fail[]

UNACCEPTABLE

Cracks: pass[☒] fail[]
Undercut: pass[☒] fail[]
Pin holes: pass[☒] fail[]
Overlap (cold lap): pass[☒] fail[]
Porosity (surface): pass[☒] fail[]
Coloration: pass[☒] fail[]

Qualifier Ed Dwyer Date of Test Coupon 08-09-05

Welder Barclay Elliot Date of Test Coupon 08-09-05

The above named individual is qualified in accordance with AWS D17.1.2001 to weld